

POPPLETON HISTORIC STUDY

B-2652

MAG#0426525404

<u>Block</u>	<u>Lot</u>	<u>Address</u>
219	48-51	40-46 S. Poppleton Street

<u>Approximate age</u>	<u>1800-1845</u>	<u>1845-1860</u>	<u>1865-1880</u>	<u>1880-1896</u>	<u>1896-on</u>
------------------------	------------------	------------------	------------------	------------------	----------------

<u>Rating</u>	<u>Architectural</u>	<u>Condition</u>
A	Significant-save	good fair poor bad
B	Quality-Indiv./groups-save	good fair poor bad
C	Important to street/groups	good fair poor bad
D	Insignificant/detrimental	good fair poor bad

Notable features:

Number 40 is vacant; it has some nice iron work of two periods, the railing c. 1845, the steps c. 1865, which should be protected. Number 46 has wall cracks but seems to be maintained quite well. Number 44 is formstoned and in good to fair condition. Number 42 has a remodelled front, new windows and arched door, which may or may not be original; it is done in good taste and excellent maintenance.

A nice group. Number 40 should be rehabilitated.


Environmental context:

Number 40 blocked up and in bad condition. School buildings and yard behind it. Street needs trees. Across-street are houses.



B-2652

40-46 S. Poppleton Street (44-46 demolished)
Sanborn Maps



B-2652
40-46 S. Poppleton Street (44-46 demolished)
Block 0219, Lots 048-051
Baltimore City
Baltimore West Quad

